



ENQUIRY REF. No.	K-E&P/SR/2217/2024-25
DATE	10.01.2025
DUE DATE	12.01.2025 till 23:59 HRS

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it. Mentioned other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for the below Supply or Service

SI No	Item Code	Item Description	Uom	Qty
		REPAIRING OF DOUBLE DOOR AUTOCLAVE'S HMI		
01	---	THE HMI SCREEN IS FLICKERING,DUE TO THIS THE HMI DISPLAY IS NOT BEEN ABLE TO OPERATE MODEL:KTP700 BASIC,6AV2 123-2GB03-0AXO,MAKE:SIEMENS	NOS.	01

DETAILS AS MENTIONED IN THE REPAIR ADVICE NOTE ENCLOSED

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post or by Hand in sealed cover to below office address or email to puren@gmail.com:

M/s. Karnataka Antibiotics and Pharmaceuticals Limited
Plot No.37, Arka The Business Centre, NTTF Main Road, Peenya Industrial Area
2nd Phase, Bengaluru-560058 Ph. No.080-23571590

NOTE:

01. PLEASE VISIT OUR SITE FOR BETTER UNDERSTANDING THE SCOPE OF WORK
02. IF YOU ARE NOT PARTICIPATING IN THE TENDER PLEASE SEND A REGRET LETTER.
03. VENDOR HAS TO QUOTE AS PER OUR TENDER IN YOUR COMPANY LETTER HEAD.

IF YOU NEED ANY CLARIFICATION, PLEASE CONTACT US.

Thanking you,

Yours faithfully,
For KARNATAKA ANTIBIOTICS
& PHARMACEUTICALS LIMITED

YUVARAJA. M
DY. MANAGER – PURCHASE DEPT.
MOB: 9945317873

154

KARNATAKA ANTIBIOTICS AND PHARMACEUTICALS LIMITED

REPAIR ADVICE NOTE/INTER DEPARTMENTAL NOTE

Page : 1 of 1

From Dept : E&P DEPT.

RAN Number : 2025F00052

To Dept : PURCHASE DEPT.

For Dept : DPP3 MICROBIOLOGY

RAN Date : 27/12/2024

Budget Type : Operational Budget

Status : GENERATED

Sub Matter : REPAIRING OF DOUBLE DOOR AUTOCLAVE'S HMI.

Engg Name : SHIVACHIDAMBARA

Mob Numbr : 8892343950

SI No Advice Description

- 1 THE HMI SCREEN IS FLICKERING, DUE TO THIS THE HMI DISPLAY IS NOT BEEN ABLE TO OPERATE.
- 2 MODEL: KTP700 BASIC, 6AV2 123-2GB03-0AX0, MAKE: SIEMENS

REMARKS

SI No RAN Note

- 1 VENDOR HAS TO VISIT THE SITE TO UNDERSTAND THE ISSUE.
- 2 THE HMI SHOULD BE REPAIRED AND HANDED OVER WITH PROPER FUNCTIONING & PROGRAM SHOULDN'T BE CHANGI
- 3 IF THE PROGRAM GOT ERASED/DELETED WHILE REPAIRING, THEN VENDOR IS RESPONSIBLE TO MAKE THE REPROGR/
- 4 SERVICE REPORT ENCLOSED. *A NOTE ENCLOSED.*