



**KARNATAKA ANTIBIOTICS &
PHARMACEUTICALS LIMITED**

(A Government of India Enterprise)

ENQUIRY REF. No.	K-E&P/SR/0305/2024-25
DATE	16/05/2024
DUE DATE	22/05/2024

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it/ OR MAIL, with other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for below mentioned material/s

SL.NO	ITEM DESCRIPTION	UOM	QTY
1	DPP1 STERILE AREA AHU REPAIR WORK	NOS	01

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post to below office address:

M/S.KARNATAKA ANTIBIOTICS AND PHARMACEUTICALS LIMITED
Plot No.37, Arka the Business Centre
NTTF Main Road, Peenya Industrial Area
2nd phase, Bangalore-560058
Ph.No.080-23571590

OR you can also mail us to our email: puren@kaplindia.com

NOTE:

1. PLEASE VISIT OUR SITE FOR BETTER UNDERSTANDING THE SCOPE OF WORK AND HAVE AN MOM COPY WITH KAPL TEAM BEFORE SENDING QUOTATION.
2. IF YOU ARE NOT PARTICIPATING IN THE TENDER PLEASE SEND A REGRET LETTER.
3. VENDOR HAS TO QUOTE AS PER BOQ ONLY IN YOUR COMPANY LETTER HEAD.
4. SPECIFICATION - ONE SHEET ATTACHED.

Thanking you,

Yours faithfully,
For KARNATAKA ANTIBIOTICS
& PHARMACEUTICALS LIMITED


YUVARAJA M
DEPUTY MANAGER PURCHASE DEPT
MOB: 994531787

Sl.No: K-E&P/DPP1-38

29
Date: 08/05/2024

REPAIR ADVICE NOTE

To: Purchase Dept.	Through: DGM (KDP)	From: E&P
--------------------	--------------------	-----------

Dear Sir,


Sub: **DPP1 sterile area AHU repair work.**

With respect to the above subject please call the vendor for sterile area AHU repair work.

- a. AHU double-skinned construction panels (pre coated GI Sheet & inner skin being of plain GI Sheet) are damaged needs to rectify by fixing new panels with proper support. The unit panels skin thickness should be not less than 0.8 mm for outer skin and 0.8 mm for inner skin. All panels shall be sealed (anti fungicide sealant material) against the framework.
- b. Damper needs to change
 - i. Fresh air damper
 - ii. Supply air damper
 - iii. Return air damper
- c. Cooling coil descaling
- d. Drain Tray needs to change for new

For technical clarification contact details,

1. Naveen Kumar H V 8123707510
2. Narendra Prasad B 7795328732


E (HVNK)


DM (MK)