



**KARNATAKA ANTIBIOTICS &  
PHARMACEUTICALS LIMITED**

(A Government of India Enterprise)

ENQUIRY REF. No.	K-E&P/SR/1523/2024-25
DATE	14.10.2024
DUE DATE	16.10.2024 till 1:00 PM

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it. Mentioned other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for the below Supply or Service

Sl No	Item Code	Item Description	Uom	Qty
01	---	DOUBLE DOOR AUTO CLAVE ISSUE REFER RAN ATTACHED FOR PROBLEMS	NO.	01

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post or by Hand in sealed cover to below office address or email to purenp@gmail.com:

**M/s. Karnataka Antibiotics and Pharmaceuticals Limited**  
**Plot No.37, Arka The Business Centre,NTTF Main Road, Peenya Industrial Area**  
**2<sup>nd</sup> Phase, Bengaluru-560058 Ph. No.080-23571590**

NOTE:

01. PLEASE VISIT OUR SITE FOR BETTER UNDERSTANDING THE SCOPE OF WORK
02. IF YOU ARE NOT PARTICIPATING IN THE TENDER PLEASE SEND A REGRET LETTER.
03. VENDOR HAS TO QUOTE AS PER OUR TENDER IN YOUR COMPANY LETTER HEAD.

IF YOU NEED ANY CLARIFICATION, PLEASE CONTACT US.

Thanking you,

Yours faithfully,  
For KARNATAKA ANTIBIOTICS  
& PHARMACEUTICALS LIMITED

YUVARAJA. M  
DY. MANAGER – PURCHASE DEPT.  
MOB: 9945317873

V.V. Urgent

Date: 11/06/2024

REPAIR ADVICE NOTE

To: Purchase Dept.		From: E&P
-----------------------	--	-----------

Through: DGM (KDP)

Agm (BR)

Photo needed, we have

Dear Sir,

Next week with Gmp Audit, speed up the process at the audit

Sub: OSD department – **DOUBLE DOOR AUROCLAVE ISSUE**

At Microbiology section Double Door Autoclave there are many number of issues which needs to be rectified as soon as possible. Please call PVT LTD) vendor for 4 days to rectify this below mentioned issues.

W.D. 11/6/24

LIST OF PROBLEMS:

- During sterilization time – drain temp and other chamber temperature sensors are not matching.
- During cycle operation the drain temperature drops down.
- After closing the door air pressure is not building in the gasket and while door opening the door air doesn't vent.
- Air leakage is observed in door pneumatic piston rod.
- While opening load door, both doors air pressure reduces to zero.
- Chamber pressure at chamber will attain temperature reading of 124 degrees centigrade even at low pressure reading of 0.2 to 0.4 bar. This needs to be rectified whereas we need temperature to attain at pressure of 1 to 1.3 bar.
- Proper training need to be given for operators to avoid operational problems, the concerned operator to be thoroughly educated.

No. 421A  
P.S. obtained  
piston  
approved  
25/9

MACHINE DETAILS:

- CODE: 24SR/SPL/V-SLD-DD/HP/HV/M150/GMP.
- SERIAL NO: 167

KAPL MATERIALS  
24 SEP 2024  
ISSUED ON