



ENQUIRY REF. No.	KAPL/EL/012/1814
DATE	14.11.2024
DUE DATE	15/11/2024(13.00HRS)

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it/ OR MAIL, with other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for below mentioned material/s.

SL. NO.	ITEM CODE	ITEM DESCRIPTION	UOM	QTY.
01	EAPCSC3001	ASSEMBLY SENSOR CHASSIS, CODE:2088577-01, MDL:6015P	NOS	01

1. Please ensure that your offer reaches us on or before Due Date by courier OR Speed post OR you can also mail us to our email: puren@kaplindia.com.
2. Please send your quotation mentioning our item code.

OTHER TERMS:

- | | |
|---------------------------------|------------------|
| 1. F.O.R TERMS | : DOOR DELIVERY |
| 2. GST % | : PLEASE SPECIFY |
| 3. PACKING & FORWARDING CHARGES | : NOT APPLICABLE |
| 4. CREDIT PERIOD | : 30 DAYS |
| 5. DELIVERY OFFERED | : PLEASE SPECIFY |

NOTE: IN CASE YOU ARE NOT QUOTING PLEASE SEND THE REGRET LETTER.

Thanking you,

Yours faithfully,
For KARNATAKA ANTIBIOTICS
& PHARMACEUTICALS LIMITED

YUVARAJA M
DEPUTY MANAGER PURCHASE DEPT



March 14, 2023

TO WHOM IT MAY CONCERN

We, M/s Beckman Coulter, Inc., USA, 5350 Lakeview Parkway South Drive, Indianapolis, IN 46268, USA, do hereby confirm that the company mentioned below:

**SHREEDHAR INSTRUMENTS
16, SHREEJI KRUPA SOCIETY, GOTRI ROAD
390023 VADODARA - INDIA**

is our distributor, authorized to promote, sell and supply the following Beckman Coulter product line in India:

LIFE SCIENCE : Particle Counting:

MetOne

Hiac Fluid

Power Hiac Life

Science

Particle Characterization

Personal CA Systems

Anatel range of TOC / PAT700 TOC

We hereby confirm our support for warranty, spares and after-sales service for our products supplied through them.

As per terms and conditions in our Distributor Agreement valid until 31 December 2024.

Note: Beckman Coulter, Inc. reserves the right to change the authorized distributor and shall intimate the authority as soon as possible in case of any change.

Yours sincerely,

For Beckman Coulter, Inc., USA

DocuSigned by:
Michelle Caron

Signed:

Full Name: Michelle Caron

Address: 5350 Lakeview Parkway South Drive, Indianapolis, IN 46268, USA

Fax no: N/A

e-mail: mcaron@beckman.com

Date: 14-Mar-2023



SERVICE REPORT

CUSTOMER DETAILS

Date : 25/04/2024

Customer Name : Karnataka Antibiotics & Pharmaceuticals Limited

Contact Person : Mr Sagar

Customer Address :

No 14, Phase II Peenya Industrial Area Bangalore-560058
Karnataka India

Designation : Manager

Department : Engg

Tel No. : Mo. : 9513399912

Email : production@kaplindia.com

INSTRUMENT DETAILS

Call No	Call Type	Item Code	Item Name	Serial No.	PO Ref. No.
856	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	1706564026	
858	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	2008564010	

Problem Reported :
Sensor Contamination

Action Taken (Resolution) :

The above mentioned instrument is sensor contamination.
Instrument is not showing any count.
Sensor cleaning process was done.
Rectification purpose checked the instrument and found sensor and PCBA board is faulty.
So we suggested to replace the board and sensor for good life of the instrument

General material
↓
Electricals

SPARE PARTS REPLACED / RECOMMENDED

EAPCSC3001

Call No	Item Type	Instrument Item Code	Instrument Item Name	Spare Item Code	Spare Item Name	Spare Item Managed By	Spare Item Sr. / Batch No.	Qty.	Transaction Type	Lease Days
856	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088577-01	oo ASSEMBLY, SENSOR CHASSIS	NONE		1.00	Paid	0
858	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088360-01	PCBA, I/O CARD 4-20mA, 4 CHANNEL	SERIAL		1.00	Paid	0

Engineer Remarks : Suggested to replace the board and sensor

Customer Remarks :

Engineer Name : S. Surjith

Concern Name :

Engineer Signature :

Customer Signature :

EAPC PCB300

Vadodara H.O. : 16, Shreeji Krupa Society, Opp.MGVCL Circle Office, B/h Kalpvruksh Building, Gotri Road, Vadodara - 390 023.
Mobile : +91 98245 10383, Email : sales@shreedhargroup.com
Ahmedabad : 6, Ruchi Apartment, 36 Swastik Society, Nr. Swastik Cross Road, Navrangpura, Ahmedabad - 380009.
Phone : 079-26444603, Email : sales@shreedhargroup.com
Hyderabad : 2D, 2nd floor, Movva Nest, Opp. Vijetha Super Market, Near Nizampet X Road, Hyderabad - 500072.
Phone : 040-40159590, Email : hydoffice@shreedhargroup.com
Bangalore : Flat no. 301, Synergy Sunshine apartment, 13 Main Road, Nobo Nagar, Bannerghatta Road, Bangalore - 560076



SERVICE REPORT

CUSTOMER DETAILS

Date : 25/04/2024

Customer Name : Karnataka Antibiotics & Pharmaceuticals Limited

Customer Address :
No 14, Phase II Peenya Industrial Area Bangalore-560058
Karnataka India

Contact Person : Mr Sagar

Designation : Manager

Department : Engg

Tel No. : Mo. : 9513399912

Email : production@kaplindia.com

INSTRUMENT DETAILS

Call No	Call Type	Item Code	Item Name	Serial No.	PO Ref. No.
856	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	1706564026	
858	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	2008564010	

Problem Reported :
Sensor Contamination

Action Taken (Resolution) :

The above mentioned instrument is sensor contamination.
Instrument is not showing any count.
Sensor cleaning process was done.
Rectification purpose checked the instrument and found sensor and PCBA board is faulty.
So we suggested to replace the board and sensor for good life of the instrument


SPARE PARTS REPLACED / RECOMMENDED

Call No	Item Type	Instrument Item Code	Instrument Item Name	Spare Item Code	Spare Item Name	Spare Item Managed By	Spare Item Sr. / Batch No.	Qty.	Transaction Type	Lease Days
856	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088515-SP	ASSEMBLY, SENSOR.	NONE		1.00	Paid	0
858	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088180-01	ee SI, PCBA Controller	SERIAL		1.00	Paid	0

Engineer Remarks : Suggested to replace the board and sensor

Engineer Name : S. Surjith

Engineer Signature :



Customer Remarks :

Concern Name :

Customer Signature :

Vadodara H.O. : 16, Shreeji Krupa Society, Opp.MGVCL Circle Office, B/h Kalpvruksh Building, Gotri Road, Vadodara - 390 023.
Mobile : +91 98245 10383, Email : sales@shreedhargroup.com
Ahmedabad : 6, Ruchi Apartment, 36 Swastik Society, Nr. Swastik Cross Road, Navrangpura, Ahmedabad - 380009.
Phone : 079-26444603, Email : sales@shreedhargroup.com
Hyderabad : 2D, 2nd floor, Movva Nest, Opp. Vijetha Super Market, Near Nizampet X Road, Hyderabad - 500072.
Phone : 040-40159590, Email : hydoffice@shreedhargroup.com
Bangalore : Flal no. 301, Synergy Sunshine apartment, 13 Main Road, Nobo Nagar, Bannerghatta Road, Bangalore - 560076

Visit us at: www.shreedhargroup.com



SERVICE REPORT

CUSTOMER DETAILS

Date : 25/04/2024

Customer Name : Karnataka Antibiotics & Pharmaceuticals Limited

Contact Person : Mr Sagar

Customer Address :

No 14, Phase II Peenya Industrial Area Bangalore-560058
Karnataka India

Designation : Manager

Department : Engg

Tel No. : Mo. : 9513399912

Email : production@kaplindia.com

INSTRUMENT DETAILS

Call No	Call Type	Item Code	Item Name	Serial No.	PO Ref. No.
856	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	1706564026	
858	Repair	2088615-PF-EA	MetOne Online APC Model 6015P	2008564010	

Problem Reported :

Sensor Contamination

Action Taken (Resolution) :

The above mentioned instrument is sensor contamination.

Instrument is not showing any count.

Sensor cleaning process was done.

Rectification purpose checked the instrument and found sensor and PCBA board is faulty.

So we suggested to replace the board and sensor for good life of the instrument

SPARE PARTS REPLACED / RECOMMENDED

Call No	Item Type	Instrument Item Code	Instrument Item Name	Spare Item Code	Spare Item Name	Spare Item Managed By	Spare Item Sr. / Batch No.	Qty.	Transaction Type	Lease Days
856	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088515-SP	ASSEMBLY, SENSOR.	NONE		1.00	Paid	0
858	Recommendation	2088615-PF-EA	MetOne Online APC Model 6015P	2088180-01	ee SI, PCBA Controller	SERIAL		1.00	Paid	0

Engineer Remarks : Suggested to replace the board and sensor

Customer Remarks :

Engineer Name : S. Surjith

Concern Name :

Engineer Signature :

Customer Signature :

Vadodara H.O. : 16, Shreeji Krupa Society, Opp. MGVCL Circle Office, B/h Kalpvruksh Building, Gotri Road, Vadodara - 390 023.

Mobile : +91 98245 10383, Email : sales@shreedhargroup.com

Ahmedabad : 6, Ruchi Apartment, 36 Swastik Society, Nr. Swastik Cross Road, Navrangpura, Ahmedabad - 380009.

Phone : 079-26444603, Email : sales@shreedhargroup.com

Hyderabad : 2D, 2nd floor, Movva Nest, Opp. Vijetha Super Market, Near Nizampet X Road, Hyderabad - 500072.

Phone : 040-40159590, Email : hydoffice@shreedhargroup.com

Bangalore : Flat no. 301, Synergy Sunshine apartment, 13 Main Road, Nobo Nagar, Bannerghatta Road, Bangalore - 560076

Visit us at: www.shreedhargroup.com