



**KARNATAKA ANTIBIOTICS &  
PHARMACEUTICALS LIMITED**

(A Government of India Enterprise)

ENQUIRY REF. No.	K-E&P/SR/2593/2024-25
DATE	11.03.2025
DUE DATE	19.03.2025 till 1:00 PM

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it. Mentioned other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for the below Supply or Service

SI No	Item Code	Item Description	Uom	Qty
01	----	17.5 HP/30 STAGE BOREWELL PUMPSET REPAIR WORK (BOQ ATTACHED)	NOS.	01

**DETAILS AS MENTIONED IN THE REPAIR ADVICE NOTE ENCLOSED**

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post or by Hand in sealed cover to below office address

*M/s. Karnataka Antibiotics and Pharmaceuticals Limited  
Plot No.37, Arka The Business Centre, NTTF Main Road, Peenya Industrial Area  
2<sup>nd</sup> Phase, Bengaluru-560058 Ph. No.080-23571590*

NOTE:

01. PLEASE VISIT OUR SITE FOR BETTER UNDERSTANDING THE SCOPE OF WORK
02. IF YOU ARE NOT PARTICIPATING IN THE TENDER PLEASE SEND A REGRET LETTER.
03. VENDOR HAS TO QUOTE AS PER OUR TENDER IN YOUR COMPANY LETTER HEAD.
04. QUOTATION MUST BE SUBMITTED IN TWO SEALED COVERS (TECHNICAL & COMMERCIAL BID) SEPARATELY AND TO BE PLACED IN ONE ENVELOP OR ELSE YOUR PROPOSAL WILL NOT BE CONSIDERED.

IF YOU NEED ANY CLARIFICATION, PLEASE CONTACT US.

Thanking you,

Yours faithfully,  
For KARNATAKA ANTIBIOTICS  
& PHARMACEUTICALS LIMITED

  
YUVARAJA. M

DY. MANAGER – PURCHASE DEPT.  
MOB: 9945317873

ENP

RAN Number : 2025F00089

PURCHASE

For Dept : FACTORY

RAN Date : 28/02/2025

Type : Capital Budget

Status : GENERATED

Matter : 17.5 HP/30 STAGE BOREWELL PUMPSET REPAIR WORK.

Engg Name : SOMASHEKARA HR

Mob Numbr : 7899157735

**SI No Advice Description**

- 1 17.5HP/30 STAGE V6 NOTCH BOREWELL PUMPSET REPAIR WORK.
- 2 INCLUDING IF ANY RELATED DAMAGED SPARE PARTS, HIDDEN CHARGES WILL NOT ENTERTAINED
- 3 BOQ ATTACHED FOR REFERENCE.

**REMARKS****SI No RAN Note**

- 1 BEFORE QUOTING CONTRACTOR HAS TO VISIT THE SITE TO UNDERSTAND THE SCOPE OF THE WORK.
- 2 LABOUR AND TRANSPORTATION WORK INCLUDING VENDOR SCOPE.
- 3 IF ANY MISSING WORK TO BE INCLUDING, HIDDEN CHARGES WILL NOT ENTERTAINED.
- 4 IF ANY ELECTRICAL WORK ARISE, IT SHOULD BE INCLUDING VENDOR SCOPE.
- 5 SERVICE REPORT TO BE SUBMITE TO FACTORY ALING WITH REPAIRED PUMPSET.

## KARNATAKA ANTIBIOTICS AND PHARMACEUTICALS LTD, PEENYA

## BOQ for 17.5 HP Borewell Pumpset Repair Work.

SI No	Description	Unit	Quantity	Unit Rate	Amount
1	Existing removed Motor Pump of 17.5 Hp/30 stage , V6 notch pumpset if burnt out needs to repair /Rewinding work to carry out including damaged spare parts etc..complete as per the specification including necessary fittings.	Set	1		
TOTAL AMOUNT					
GST %					
GRAND TOTAL AMOUNT					

Note:-

- 1) Before quoting, Contractor has to visit the site to understand the scope of the work.
- 2) If any Electrical work will arise, it should be included in Contractor scope of work
- 3) Safety norms to be taken care by Contractor only
- 4) ESI & Other Statutory requirements to be completed
- 5) Labour and transportation charges included vendor scope.

  
29/12/25

JE(SHR)

