

KARNATAKA ANTIBIOTICS & PHARMACEUTICALS LIMITED

(A Government of India Enterprise)

ENQUIRY REF. No.	K-E&P/SR/1306/2024-25		
DATE	06.09.2024		
DUE DATE	10.09.2024 till 1:00 PM		

Dear Sir.

Please submit your lowest and competitive offer in a SEALED ENVOLOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it. Mentioned other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for the below Supply or Service

SI No	Item Code	Item Description	Uom	Qty
1		COMPREHENSIVE AMC FOR UPS SYSTEM FOR CEPHALOSPORIN BLOCK AT DPP-3	Nos.	02

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post or by Hand in sealed cover to below office address or email to purenp@gmail.com:

M/s. Karnataka Antibiotics and Pharmaceuticals Limited
Plot No.37, Arka The Business Centre, NTTF Main Road, Peenya Industrial Area
2nd Phase, Bengaluru-560058 Ph. No.080-23571590

NOTE:

- 01. PLEASE VISIT OUR SITE FOR BETTER UNDERSTANDING THE SCOPE OF WORK
- 02. IF YOU ARE NOT PARTICIPATING IN THE TENDER PLEASE SEND A REGRET LETTER.
- 03. VENDOR HAS TO QUOTE AS PER OUR TENDER IN YOUR COMPANY LETTER HEAD.

IF YOU NEED ANY CLARIFICATION, PLEASE CONTACT US.

Thanking you,

Yours faithfully,

For KARNATAKA ANTIBIOTICS & PHARMACEUTICALS LIMITED

YUVARAJA. M

DY. MANAGER - PURCHASE DEPT.

MOB: 9945317873

KARNATAKA ANTIBIOTICS AND PHARMACEUTICALS LTD., PEENYA BANGALORE

NC - AMC FOR 10KVA & 15KVA UPS system at DPP-III Section

ANNEXURE - I

SI. No.	Description	Unit	QTY.
1	10KVA UPS System Model No: SURT10000UXI	No.	1
	MAKE: APC	INO.	T
2	15KVA UPS System		
	Model No: SURT15KUXI	No.	1
	MAKE: APC		

NOTE:

- 1. Unlimited breakdown calls to be attended, calls to be attended within 24hrs from the time of breakdown call.
- 2. Quarterly preventive maintenance must be done per year (4times).
- 3. Comprehensive AMC which includes 100% parts of the UPS system covered under vendor scope (except switch gears, wound components & batteries). If the battery condition is poor based on the report the batteries has to be replaced by vendor (Batteries will be provided by KAPL)
- 4. The safety precaution should be taken care by vendor at work place.