

KARNATAKA ANTIBIOTICS & PHARMACEUTICALS LIMITED

(A Government of India Enterprise)

ENQUIRY REF. No.	KAPL/EL/012/2347
DATE	05.02.2025
DUE DATE	07.02.2025(13.00HRS)

Dear Sir,

Please submit your lowest and competitive offer in a SEALED ENVELOPE, DULY SUPERSCRIBING OUR ABOVE ENQUIRY REF. NO., DATE and DUE DATE on it/ OR MAIL, with other details of F.O.R terms, Taxes, Credit period, Delivery offered, Name of the Make, Detailed Specification etc., for below mentioned material/s.

SL. NO.	ITEM CODE	ITEM CODE ITEM DESCRIPTION		QTY.
01	EAPCSC3001	ASSEMBLY SENSOR CHASSIS,CODE:2088577-01,MDL:6015P	NOS	01

Please ensure that your offer reaches us on or before Due Date by courier OR Speed post OR you can also mail us to our email: purenp@kaplindia.com.

OTHER TERMS:

1. F.O.R TERMS

2. GST %

3. PACKING & FORWARDING CHARGES

4. CREDIT PERIOD

5. DELIVERY OFFERED

: DOOR DELIVERY

: PLEASE SPECIFY

: NOT APPLICABLE

: 30 DAYS

: PLEASE SPECIFY

NOTE: IN CASE YOU ARE NOT QUOTING PLEASE SEND THE REGRET LETTER.

NOTE: PLEASE MENTION OUR CODE IN YOUR QUOATION

Thanking you,

Yours faithfully, For KARNATAKA ANTIBIOTICS & PHARMACEUTICALS LIMITED

Ny 1 string

YUVARAJA M

DEPUTY MANAGER PURCHASE DEPT

MOB:- 9945317873

1.

SERVICE REPORT

CUSTOMER DETAILS

Date:

25/04/2024

Customer Name: Karnataka Antibiotics &

No 14, Phase II Peenya Industrial Area Banglore-560058

Pharmaceuticals Limited

Customer Address:

Karnataka India

Contact Person: Mr Sagar

Designation: Manager

Department : Engg

Tel No.: Mo.: 9513399912

Email: production@kaplindia.com

INSTRUMENT DETAILS

Call No Call To	Call Type	Item Code	D		
856			Item Name	Serial No.	DO D 111
030	Repair	2088615-PF-EA	MetOne Online APC Model 6015P		PO Ref. No.
858	Repair	00000		1706564026	
	Daniel I		MetOne Online APC Model 6015P	2008564010	

Problem Reported:

Sensor Contamination

Action Taken (Resolution):

The above mentioned instrument is sensor contamination.

Instrument is not showing any count

Sensor cleaning process was done.

Rectification purpose checked the instrument and found sensor and PCBA board is faulty.

So we suggested to replace the board and sensor for good life of the instrument

SPARE PARTS REPLACED / RECOMMENDED

		TO TO LEG / NECOMMENDED							
Type	Instrument Item Code	Instrument Item Name	Spare Item Code	Spare Item Name		Spare Item Sr. / Batch No.	,.	Transact ion Type	Lease Days
Recommend ation	2088615-PF-EA	MetOne Online APC Model 6015P	2088577-01	oo ASSEMBLY	NONE	+	4.00		
Recommend 2088615-PF-EA alion			SENSOR CHASSIS		- 1	1,00	Paid	0	
	Melione Online And	2088360-01	PCBA, I/O CARD 4-20mA, 4 CHANNEL	SERIAL	,	1,00	Paig	0	
	Recommend ation Recommend ation	Type Item Code Recommend ation 2088615-PF-EA ation	Type Item Code Name Recommend ation 2088615-PF-EA MetOne Online APC Model 6015P Recommend ation 2088615-PF-EA MetOne Online APC Model 6015P	Item Type Instrument Item Code Instrument Item Name Spare Item Code Recommend ation 2088615-PF-EA MetOne Online APC Model 6015P 2088577-01 Recommend ation 2088615-PF-EA MetOne Online APC Model 6015P 2088360-01	Item Type Instrument Item Name Spare Item Code Spare Item Name Spare Item Code Spare Item Name	Item Type Item Code Instrument Item Name Spare Item Code Spare Item Name Spare Item Name Spare Item Name Item Name Spare Item Name Item Name Spare Item Name Item Name Item Name Spare Item Name	Item Type Instrument Item Name Spare Item Code Item Name Spare Item Code Spare Item Sr. / Batch Managed By Recommend ation 2088615-PF-EA MetOne Online APC Model 6015P 2088360-01 PCBA, I/O CARD SERIAL	Item Type Item Code Item Name Spare Item Code Spare Item Name Spare Item Sr. / Batch No. Recommend ation 2088615-PF-EA MelOne Online APC Model 6015P Sexpand Second ation MelOne Online APC Model 6015P 2088360-01 PCBA, I/O CARD SERIAL 1000	Item TypeInstrument Item CodeInstrument Item NameSpare Item CodeSpare Item NameSpare Item Item Managed BySpare Item Sr. / Batch No.Qty.Transact ion TypeRecommend ation2088615-PF-EAMetOne Online APC Model 6015P2088577-01oo ASSEMBLY, SENSOR CHASSISNONE1,00PaidRecommend ation2088615-PF-EAMetOne Online APC Model 6015P2088360-01PCBA, I/O CARDSERIAL1.00Posta

sensor

Engineer Name: S. Surjith

Engineer Signature:

Customer Remarks:

Concern Name:

Customer Signature:

CARCLERS



March 14, 2023



TO WHOM IT MAY CONCERN

We, M/s Beckman Coulter, Inc., USA, 5350 Lakeview Parkway South Drive, Indianapolis, IN 46268, USA, do hereby confirm that the company mentioned below:

SHREEDHAR INSTRUMENTS 16, SHREEJI KRUPA SOCIETY, GOTRI ROAD 390023 VADODARA - INDIA

is our distributor, authorized to promote, sell and supply the following Beckman Coulter product line in India:

LIFE SCIENCE: Particle Counting:

MetOne Hiac Fluid Power Hiac Life Science Particle Characterization Personal CA Systems Anatel range of TOC/PAT700 TOC

We hereby confirm our support for warranty, spares and after-sales service for our products supplied through them.

As per terms and conditions in our Distributor Agreement valid until 31 December 2024.

Note: Beckman Coulter, Inc. reserves the right to change the authorized distributor and shall intimate the authority as soon as possible in case of any change.

Yours sincerely,

For Beckman Coulter, Inc., USA



Full Name: Michelle Caron

Address: 5350 Lakeview Parkway South Drive, Indianapolis, IN 46268, USA

Fax no: N/A

e-mail: mcaron@beckman.com Date:14-Mar-2023